

**DEPARTMENT OF TRANSPORTATION****DIVISION OF ENGINEERING SERVICES**

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-026107**Date Inspected:** 20-Jun-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Corporation, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Mai Quin Li**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Bike Path Hand Rails Components**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Delbert Humphrey was present during the times noted above for observations relative to the work being performed at ZPMC.

Bay #14

NDT

The following Non Destructive Testing (NDT) inspection carried out as per the ZPMC submitted Notification No. 09520.

This QA inspector performed Magnet Particle Testing (MT) of approximately 15% of an area that has been previously tested and accepted by ZPMC Quality Control (QC) personnel. This QA Inspector generated an MT report for this date. Time of inspection was 14:30 hours. The members are identified as follows OBG Component. The weld designations reviewed are as follow: SEG3020W-191, 178, 107, 106, 090, 105, 003, 079, 081, 087, 107, 106, 090, 105, 003, 079, 081, 087, 107, 106, 090, SEG3020V-102, 106, 105, SEG3020T-135, 088, 108, 110, 090, 092, 093, 091, 111, 089, 311, 318, SEG3020T-135, 088, 108, 110, 090, 092, 093, 091, 111, 089, 311, 318, SEG3020S-131, 133, 127, 129, 136, 128, 130, 134, 132, 054, SEG3020Q-178, 180, 174, 176, 182, 189, SEG3020R-185, 153, 155, 187, 189, SEG3020X-075, 076, 077, 080, 083, SEG3020L-041, SEG3020D-234, 238, 242, 246, 250, 254, 258, 262, 266, 270, 274, 278, 282, 286, 290, 294, 298, 302, DP3172-001-085, 059, DP3174-001-039, 085.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

### Summary of Conversations:

No relevant conversations were reported on this date.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 15000422372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Humphrey, Delbert	Quality Assurance Inspector
<b>Reviewed By:</b>	Hall, Steven	QA Reviewer

---